




Deadline March 31st 2010



Don't waste time

Compliance Made easy

1. Training
2. Hazardous Waste Removal
3. Documentation

Soltec (Ireland) Ltd

Telephone: 044 9335133

Zone A, Mullingar Business Park, Mullingar, Co. Westmeath

www.soltec.ie

info@soltec.ie

Nationwide Service

Compliance: It's as Easy as 1,2,3!

Step 1: Training

The first step is to become aware of the regulations and the obligations it imposes on Bodyshop owners. All products containing VOC's must be compliant, and any non-compliant product must be removed from stock and treated as Hazardous Waste. Staff should be trained to identify Haz Waste and know how to handle and store it. i.e. make sure all waste is clearly identifiable by labels and stored in containers with lids. Soltec regularly supply and provide training in the use of spill kits to bodyshops, as they prove to be indispensable in the case of an accident. Soltec provide training for the use of all our products to first time customers and also the relevant training certificates.

Step 2: Hazardous Waste Removal

It is essential to use a reputable, licensed permitted waste collection company such as Soltec, when disposing of your Hazardous Waste. Waste should be stored in clearly labelled Un Approved containers such as barrels for liquid or solvent waste and in the case of Solid Waste, in any of Soltec's own range of Haz Products; The HazBag, HazBox and HazBin. All Hazardous Waste transported should be accompanied by a C1 form which acts like a passport for Hazardous Waste. With Soltec as your Waste Specialist, you can be assured that any waste collected will be disposed of in accordance with regulations and all documentation relating to the collection and disposal of the waste will be provided, at no extra cost.

Step 3: Documentation

One of the most important aspects of being compliant is to ensure that correct documentation is kept on site. This includes:

1. Records of all compliant product used on site.
2. Records of any training undertaken.
3. An up-to-date copy of your Waste collectors EPA Licence and Waste Collection Permit covering your area.
4. Service Record on GunWash and Distillation units
5. Copies of C1 Documentation
6. Certificates of recovery/ disposal which outline the Licence Number of site where waste is been sent

These steps can provide a useful starting point to someone undertaking their first AIC Inspection but also act as a reminder to those renewing their registration of the requirements needed to remain compliant. If you are unsure whether you are compliant and would like more information on any of the products mentioned above, contact Soltec **today!!** Log on to www.soltec.ie, call us on 044 93 35133 or email info@soltec.ie.

Soltec: 'Making Waste Work'.

Steps are intended as a guideline only and are not an interpretation of the law.